

Date: Monday, 9/10/2007 1:31:13 PM  
 User: Kim Johnston

## Process Sheet

Customer : CU-DAR001 Dart Helicopters Services	Drawing Name : CROSSBOLT SPACER
Job Number : 34508	
Estimate Number : 11010	
P.O. Number : <i>N/A</i>	Part Number : D2649
This Issue : 9/10/2007 S.O. No. : <i>N/A</i>	Drawing Number : D2649 REV B1
Prsht Rev. : NC	Project Number : <i>N/A</i>
First Issue : <i>N/A</i> Type : MACHINED PARTS	Drawing Revision : B1
Previous Run : 33214	Material : <i>N/A</i>
Written By : _____	Due Date : 9/30/2007 Qty: 400 Um: Each
Checked & Approved By : <i>[Signature]</i> 07.09.11	
Comment : Est F 02.03.26 Added turning on Cobra NG	

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	M6061T6T0375W058	6061-T6 Tube .375 x.058W
-----	------------------	--------------------------



Comment: Qty.: 0.2975 f(s)/Unit Total : 118.9860 f(s)

6061-T6 Tube .375 x.058W

Material: 6061-T6 or 5052-H32, 0.375" Dia X 0.058" Wall

Batch *M104897* 49.7'

*27.4'*

*DA 07/09/26*

2.0	HARDINGE	HARDINGE CNC LATHE SMALL
-----	----------	--------------------------



Comment: HARDINGE CNC LATHE SMALL

Machine as per folio *FA 214* on cobra machine.

*DA 07/09/26*

*RD 07/09/27*

3.0	QC2	INSPECT PARTS AS THEY COME OFF MACHINE
-----	-----	--



Comment: INSPECT PARTS AS THEY COME OFF MACHINE

*DA 07/09/26*

*RD 07/09/27*

4.0	QC8	SECOND CHECK
-----	-----	--------------



Comment: SECOND CHECK

*J.F.*

*07/09/27*

5.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: *BARCLAY*

*07/09/28*

*464*

6.0	QC21	FINAL INSPECTION/W/O RELEASE
-----	------	------------------------------



Comment: FINAL INSPECTION/W/O RELEASE

*DA 07/09/28*

Job Completion



*W 07.09.28*

# Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes ☒ No ☐ DQA: PD Date: 9/18/28  
 QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



DART AEROSPACE LTD		Work Order:	34508
Description: Crossbolt Spacer		Part Number:	D2649
Inspection Dwg: D2649      Rev: B1			Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

☒ **First Article**      ☐ **Prototype**

[illegible]


Measured by: DJP	Audited by: [Signature]	Prototype Approval:	N/A
Date: 07/09/26	Date: 07/09/26	Date:	N/A

Rev	Date	Change	Revised by	Approved
A	04.01.21	New Issue	KJ/RF 	



DESIGN <i>DM</i>	DRAWN BY <i>KE</i>	DART AEROSPACE USA, INC. FAIRCHILD INTERNATIONAL AIRPORT, WA	
CHECKED <i>DM</i>	APPROVED <i>BW</i>	DRAWING NO. D2649	REV. B SHEET 1 OF 1
DATE 98.01.14		TITLE CROSS BOLT SPACER	SCALE 1:1
A	97.03.25	NEW ISSUE	
B	98.01.14	3.180 WAS 3.230, ADD CHAMFER	
B1	<del>#</del> CP 02.06.13	REDUCE CHAMFER PER TSR 1296.	

RELEASED  
98.01.20 DS



MATERIAL: 6061-T6 (WW-T-700/6) OR 5052-H32 (WW-T-700/4)  
0.375 DIA 0.058 WALL

TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

SHOP COPY  
RETURN TO  
ENGINEERING  
UNCONTROLLED COPY  
SUBJECT TO AMENDMENT  
WITHOUT NOTICE  
WORK ORDER  
NO. 34508